# Navajo Abandoned Uranium Mine

# Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

## Mesa II Pit AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

## Part I **Site Identification, Location and Status** Site Names and ID numbers as applicable **Mine ID:** 287 Map ID: N222 **CERCLIS:** NNN000908874 Navajo Abandoned Mine Land Reclamation Program: NA-0324 Local name / Aliases: Mesa 2 Pit **Chapter and local area:** Cove Chapter County: Apache State: Arizona **Lat/Long:** 36.5303690307 N / -109.231589917 W **Nearby road and highway:** Indian Route 33 Local Post Office: Cove, AZ Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** Fee land State **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database. **Claim and operator information:** The mine site surface land status is classified as Tribal Trust Land. Historical documents showed the operator of the mine as F.A. Sutton from 1950 to 1951, and Navajo Uranium in 1951. No other historical ownership / lease information was identified in the EPA/AUM database. Number of residential structures within 200 feet of mine: None **Estimated volume of mine waste onsite:**

None

#### Part II Summary of radiological readings

#### **Highest gamma radiation measurement:**

36,525 counts per minute (cpm)

#### Describe any other radiological measurements:

A total of 446 gamma radiation measurements were collected from the mine site, ranging from 8,105 cpm to 36,525 cpm. The measurements are represented in Figures 1 and 2.


#### **Background Locations**

**Average background** = 11,120 cpm

#1 9,405 cpm #2 12,385 cpm

#### **Distribution Chart and Statistics:**

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 446

 Minimum:
 8105,00000

 Maximum:
 36525,00000

 Sum:
 7273161,00000

 Mean:
 16307,53587

 Median:
 15769,00000

 Standard Deviation:
 4043,84380

#### Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

**NAMLRP Project Number:** NA-0324

**NAMLRP Mine features:** 1 Rim Strip / Pit

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

| of any reclamation caps. Note condition of all caps. |
|--|
| Observed reclamation work and status:                |
| Adits<br>None  |
| Waste Piles<br>None                                  |
| Pits<br>None   |

## **Other Debris and Mine Features**

None

**Shafts** None

#### **Part IV**

#### Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

**0 to 200 feet:** None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

**0.25 miles to 4 miles:** None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Mesa II Pit consists of an area of 2,627.7 m<sup>2</sup>. The mine was identified as being operational from 1950 to 1951. Historical documents showed the operator of the mine as F.A. Sutton from 1950 to 1951, and Navajo Uranium in 1951. While operational, the mine had a total reported production volume of 822 tons. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

**Site Name(s):** Mesa II Pit **Chapter:** Cove

**Decision Criteria** 

Is there an unreclaimed waste pile at the site? None

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? None

Is the cap/seal functionally intact? None

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

**Summary of emergency response factors** 

None

**Summary hazard ranking system factors** 

None

**Summary of reclamation factors** 

None

### Part VI Photos



Photo 1. Mine site




Photo 2. Drainage heading down cliff area

## Part VII Contacts Reports and Information

Name: Stanley Edison (928) 871-6861 Eugene Esplain (928) 871-7331 Title or official role (if any) Navajo EPA Superfund Program Address PO Box 2946, Window Rock, AZ 86515 Information provided <u>Lead Regulatory Agency</u> Title or official role (if any) Address Telephone number\_\_\_\_\_ Information provided Title or official role (if any) Telephone number\_\_\_\_\_ Information provided\_\_\_\_\_ Name Title or official role (if any) Telephone number

Information provided\_\_\_\_\_\_

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Mesa II Pit (287)
Cove Chapter, Navajo Nation, Arizona



**Gamma Radiation Measurements** 

- < 2X Backgound</p>
- > 2X Background

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 11,120 cpm








Figure 2 - Gamma Radiation Measurements Mesa II Pit (287) Cove Chapter, Navajo Nation, Arizona



### Legend

#### **Gamma Radiation Measurements**

- 0 10,000
- 10,000 15,000
- **15,000 20,000**
- **2**0,000 50,000
- 50,000 100,000
- > 100,000



Mine Claim Boundaries

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 11,120 cpm

